

The connection stops or is unstable

The vehicle engine compartment may interfere with the bluetooth connection. This may cause poor reception between the eFlexFuel control unit and the connected mobile device.

Thick vehicle insulation or enclosed mounting of the control unit to the engine compartment can cause a poor usage.